

Statewide Survey of Historic Properties

Site Number: 326-0427.01

Survey Report for McClellanville

Tax Map No.: 764-14-00-106

Identification

Historic Name: Doar Kitchen building
Common Name: Doar Kitchen building
Address/Location: 125 Oak Street (rear) (127 Oak Street per Chas Co)
Ownership: Private
Historical Use: Domestic
Category: Building
Current Use: Domestic

National Register of Historic Places Information

SHPO National Regis DOE: Contributes to Listed District
Other Designation: contributes to a local district

Notes:

Property Description

Construction Date: c. 1870
Construction Method: frame
Historic Core Shape: rectangular
Exterior Walls: other
Stories: 1 story
Foundation: brick pier

Roof Features Shape: gable, lateral
Materials: raised seam metal
Porch Features Porch Width:
Shape:

Significant Architectural Features: Board and batten siding; 6/6 windows flank central beadboard entry door on south elevation; Windows are shuttered with vertical board shutters; interior brick chimney with gothic cap on west end of building.

Alteration Date:

Alterations: fixed light in entry door; in state of disrepair.

Photographs

Primary View:



Additional Views:



Date Recorded: 1/28/2008