

# Statewide Survey of Historic Properties

Site Number: 326-0463

## Survey Report for McClellanville

Tax Map No.: 764-14-00-079

### Identification

Historic Name:

Common Name:

Address/Location: 721 Morrison Street

Ownership: Private

Category: building

Historical Use: Domestic

Current Use: Domestic

### National Register of Historic Places Information

SHPO National Regis DOE: Contributes to Listed District

Other Designation: contributes to local district

Notes:

### Property Description

Construction Date: c. 1935

Historic Core Shape: rectangular

Stories: 1 1/2 stories

Construction Method: frame

Exterior Walls: weatherboard

Foundation: brick pier

*Roof Features* Shape: gable, lateral

*Porch Features* Porch Width: entrance bay only

Materials: composition shingle

Shape: gable

Significant Architectural Features: Engaged porch with posts across south elevation. Casement windows at center of tripartite window and at second level. Three gable dormers, two with 6/6 windows. Rear gable wing with slightly lower roofline, width of main body. Louvered vent in gambrel end; fanlight above entry door.

Alteration Date: unknown

Alterations: screened porch at rear. Porch at south infilled post 1992 survey. Central dormer appears to have been added or altered--pre-1992.

### Photographs

Primary View:



Additional Views:



Date Recorded: 11/16/2007